



Home > Recalls > 3M™ Aura™ Particulate Respirator 9322A+

3M™ Aura™ Particulate Respirator 9322A+

Date posted 7 Nov 2019



The Hazard



The nose foam may separate from the top panel of the respirators.

Without the nose foam the respirator will not fit tightly over the nose and could fail to protect the user from exposure to airborne particulates.

What to do



Stop using and quarantine affected respirators and contact your 3M distributor.

Product Identifiers

Sold between May and October 2019

3M™ Aura™ Particulate Respirator 9322A+ with the Lot Numbers listed below only:

R19132 5 001
R19131 5 001
R19131 5 002
R19131 5 003
R19131 5 004
R19131 5 005
R19131 5 006
R19131 5 007
R19131 5 008
R19130 5 008

Supplier Contact

3M New Zealand



Visit their site

Responsible Agency



MINISTRY OF BUSINESS,
INNOVATION & EMPLOYMENT
HIKINA WHAKATUTUKI

3M New Zealand Website

https://www.3mnz.co.nz/3M/en_NZ/company-nz/?utm_medium=redirect&utm_source=vanity-url&utm_campaign=3mnz.co.nz