
04 April 2022



#### FATAL ACCIDENT

#### Three workers fell from scaffold

On 28 March 2022, three workers were on a scaffold erected around a gantry structure of a dredging vessel at a shipyard. The gantry structure suddenly dropped causing part of the scaffold to be flung to the dock bottom. Two of the workers fell about 20 metres to their death, while the third worker survived with minor injuries as he managed to cling onto a part of the structure.



Damaged scaffold

Dredging vessel

Scene of the accident.

### Recommendations

Gantry structure

which dropped

Falling from height can lead to death or serious injury. To prevent similar accidents, consider the following measures:

- Structural integrity: Assess the integrity of a structure before erecting scaffolding around the structure. If the scaffolding is attached to the structure, the structure must be able to withstand the additional loading due to the weight of the scaffold, workers, tools and equipment.
- Movable parts locked in place: Lockout all movable structure parts securely to ensure there is no movement while work is in progress. Check the locking mechanism(s) regularly to confirm they are in good working condition.
- Structural support: Put in place additional supports to prevent movement of the structure.
- Fall Prevention Plan (FPP): Develop and implement a FPP and Permit-To-Work system, for all hazardous work at height. Where possible, provide independent and secure anchor points or lifelines and train workers to anchor themselves at all times when working at height.
- Safe Work Procedure (SWP): Establish and implement a SWP for carrying out work on the gantry structure and provide supervision to ensure workers follow the SWP. The SWP should include checks on structure integrity and locking mechanism(s).

For more information, please refer to WSH Council's Code of Practice for Working Safely at Heights, WSH Guidelines on Anchorage, Lifelines and Temporary Edge Protection Systems, and WSH Guidelines on Personal Protective Equipment for Work at Heights.

\* Information on the accident is based on preliminary investigations by the Ministry of Manpower as at 31 March 2022. This may be subject to change as investigations are still on-going. Please also note that the recommendations provided here are not exhaustive and they are meant to enhance workplace safety and health so that a recurrence may be prevented. The information and recommendations provided are not to be construed as implying liability on any party nor should it be taken to encapsulate all the responsibilities and obligations under the law.

Workplace injuries tend to rise around this time of the year. Remain vigilant against risks and prevent accidents.

## **Share this WSH Alert**



source of the material.








# Connect with us












**Events** on Workplace Safety and Health



address. For enquiries or feedback, please email us at contact@wshc.sg. Visit the WSH Council's <u>website</u> now for updates on WSHrelated matters, information and events.



www.wshc.sg/mentalwellbeingcampaign This WSH Bulletin is available free of charge, may be printed or downloaded onto electronic, optical or similar storage media provided that such activities are for private research, study, or in-house use only. If such material is to be copied or reproduced, users are asked to ensure that the material is reproduced accurately and not in a misleading context,

that the status of the material is identified and to acknowledge Workplace Safety & Health Council, Singapore as the